Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	545	73/800.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/19 15:30
S2	117	73/786.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/19 15:31
53	81	73/787 ccls	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/19 15:31
S4	26	73/785.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/19 15:32
S5	199	73/789 ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/19 15:35
S6	53	((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 stress) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 strain) and (x?ray "x-ray" xray) and miller	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/19 15:44
S7	9	((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 stress) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 strain) and (x?ray "x-ray" xray) and (miller near2 (index indicia))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 11:25
S8	. 8	S7 and (difraction diffraction)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/19 15:58
S9	0	((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 stress) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 strain) and (x?ray "x-ray" xray) and (miller near2 (index indicia)) and (difraction diffraction) and polycristal\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	OR	ON	2004/11/22:11:25
S10	0	((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 stress) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 monitor\$4 detect\$4 defin\$4) near3 strain\$4) and (x?ray "x-ray" xray) and (miller near2 (index indicia)) and (difraction diffraction) and (polycristal\$4 poly?cristal\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 11:28
S11	0	((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 stress) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 monitor\$4 detect\$4 defin\$4) near3 strain\$4) and (x?ray "x-ray" xray) and (miller near2 (index indicia)) and (difraction diffraction) and (polycristal\$4 poly?cristal\$4 multicristal\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 11:30
S12	0	((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 (stress strain\$4)) and (x?ray "x-ray" xray) and (miller near2 (index indicia)) and (difraction diffraction) and (polycristal\$4 poly?cristal\$4 multicristal\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 13:16
S13	0	(x?ray "x-ray" xray) and (miller near2 (index indicia)) and (difraction diffraction) and (polycristal\$4 poly?cristal\$4 multicristal\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR.	ON	2004/11/22 13:16

S14	109	("6031611" "4095103" "4489425" "5432595" "4561062" "5414747" "6311558" "4248094" "6285736" "4599563" "5446777" "6493420" "4559824" "4128762" "4287416" "5828724" "6058160" "4497209" "5442950" "5463896" "6727690" "4788702" "4916720" "5248889" "6227052" "6368711" "6428892" "4404682" "4959548" "6721393" "6750451" "6269144" "6121051" "3816747" "4796284" "3639760" "3639758" "4125771" "4402227" "6239593" "4385095" "5495331" "6192103" "6593153" "4854172" "5258091" "3846632" "4342907" "4443700" "5272746").pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 13:18
S15	134	(x?ray "x-ray" xray) and (miller near2 (index indicia)) and (difraction diffraction) and (polycrystal\$4 poly?crystal\$4 multicristal\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	OR	ON	2004/11/22 13:18
S16	14	((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 (stress strain\$4)) and (x?ray "x-ray" xray) and (miller near2 (index indicia)) and (difraction diffraction) and (polycrystal\$4 poly?crystal\$4 multicristal\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 13:23
S17	50	("6031611" "4095103" "4489425" "5432595" "4561062" "5414747" "6311558" "4248094" "6285736" "4599563" "5446777" "6493420" "4559824" "4128762" "4287416" "5828724" "6058160" "4497209" "5442950" "5463896" "6727690" "4788702" "4916720" "5248889" "6227052" "6368711" "6428892" "4404682" "4959548" "6721393" "6750451" "6269144" "6121051" "3816747" "4796284" "3639760" "3639758" "4125771" "4402227" "6239593" "4385095" "5495331" "6192103" "6593153" "4854172" "5258091" "3846632" "4342907" "4443700" "5272746").pn.	USPAT	OR	ON	2004/11/22 14:21
S18	5	S15 and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 stress) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 monitor\$4 detect\$4 defin\$4) near3 strain\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 13:18
S19	14	((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 (stress strain\$4)) and (x?ray "x-ray" xray x?radiation) and (miller near2 (index indicia)) and (difraction diffraction) and (polycrystal\$4 poly?crystal\$4 multicristal\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	OR	ON	2004/11/22 13:25
S20	14	((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 (stress strain\$4)) and (x?ray "x-ray" xray "x-radiation") and (miller near2 (index indicia)) and (difraction diffraction) and (polycrystal\$4 poly?crystal\$4 multicristal\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 13:31
S21	6	S20 and tetragon\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	OR	ON	2004/11/22 13:51
S22	3	((specimen sample piece) near3 (polycrystal\$4 poly?crystal\$4 multicristal\$4) near3 tetragon\$4) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 stress) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 monitor\$4 detect\$4 defin\$4) near3 strain\$4) and (x?ray "x-ray" xray)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 13:53
S23	3	((measur\$4 meter\$4 sens\$4 test\$4 estimat\$4 asses\$4 determin\$4 monitor\$4 detect\$4 defin\$4) near3 (polycrystal\$4 poly?crystal\$4 multicristal\$4) near3 tetragon\$4) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 detect\$4 defin\$4) near3 stress) and ((measur\$4 meter\$4 sens\$4 estimat\$4 asses\$4 determin\$4 monitor\$4 detect\$4 defin\$4) near3 strain\$4) and (x?ray "x-ray" xray)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 13:54
S24	86	378/72.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/22 14:33

S25	339	378/73.ccls.	US-PGPUB;	OR	ON	2004/11/22 14:33
			USPAT;			
	Ì		EPO; JPO;			
			DERWENT:			
			IBM_TDB			